

Inspection Photos
Location Name: 70 Ranch 10 East
Location ID: 451960



Photo #1 Wells

Inspection Photos
Location Name: 70 Ranch 10 East
Location ID: 451960



Photo #2 Unused Equipment/ Stained Soil

Photo #3 Stained soil

Inspection Photos
Location Name: 70 Ranch 10 East
Location ID: 451960



Photo #4 Oily Waste/ Unused Equipment

Photo #5 Oily Waste/ Unused Equipment

Inspection Photos
Location Name: 70 Ranch 10 East
Location ID: 451960



Photo #6 Unmarked Riser

Photo #7 Unmarked Riser