



**OIL & GAS CONSERVATION COMMISSION**  
**FIELD INSPECTION REPORT**

99999999

UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05-	123 - 5657	LEASE NAME:	McKenzie 1-A
LOCATION:	NE NW 13-9N-57	OPERATOR:	J+L
DATE:	4-23-97	INSPECTOR:	EBB
Insp. Type: HR	Insp. Status: PA	PA: <input checked="" type="radio"/> Y <input type="radio"/> N	Pass/Fail: <input checked="" type="radio"/> P <input type="radio"/> F
		Viol.: Y <input checked="" type="radio"/> N	NOV: Y <input type="radio"/> N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	grassland, cactus	
<b>Miscellaneous</b>	handowner has trash pit nearby.	

<b>CORRECTIVE ACTION REQUIRED:</b>	
Date Corrective Action Required By:	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00270696