

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:	<u>Shares containment with crude oil tanks</u>				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	

Other (Capacity) 48 BBL	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	BV CONCRETE		
Comment: Shares containment with crude oil tanks					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity) 60 BBL	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.297800,-104.543500
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 481289 Type: TANK API Number: - Status: AC Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 1/10/22 at approximately 0830hrs I, Inspector Adam Burns, Conducted an on-site inspection at Herbst C 22-24 Tank of Noble Energy Facility ID: 481289 in Weld County, Colorado. While there, I observed a facility that is SI. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.</p>	burnsa	01/11/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699105029	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5629838