

Inspection Photos
Location Name: Pronghorn F-22 PAD
Location ID: 437437



Photo 1 – Wellheads



Photo 2 – Wellheads

Inspection Photos
Location Name: Pronghorn F-22 PAD
Location ID: 437437



Photo 3 – ECDs



Photo 4 – Tank Battery

Inspection Photos
Location Name: Pronghorn F-22 PAD
Location ID: 437437



Colorado Oil and Gas Conservation Commission
40.39218, -104.20018, 4634.4ft, 214°
01/10/2022 12:14:49



Colorado Oil and Gas Conservation Commission
40.39212, -104.20024, 4622.5ft, 99°
01/10/2022 12:15:17

Photo 5 – Tank Battery Signs

Photo 6 – 60 BBLs Concrete Vaults missing Labels

Inspection Photos
Location Name: Pronghorn F-22 PAD
Location ID: 437437



Photo 7 – Tank Battery Signs

Photo 8 – Unmarked Riser South of Compressor

Inspection Photos
Location Name: Pronghorn F-22 PAD
Location ID: 437437



Photo 9 – Unmarked Riser 1” at Compressor



Photo 10 – Day Tank at Compressor Netting in disrepair

Inspection Photos
Location Name: Pronghorn F-22 PAD
Location ID: 437437



Colorado Oil and Gas Conservation Commission
40.39212, -104.2008, 4593.8ft, 310°
01/10/2022 12:20:13



Colorado Oil and Gas Conservation Commission
40.39213, -104.20079, 4595.0ft, 182°
01/10/2022 12:20:53

Photo 11 – Day Tank at Compressor Netting in disrepair

Photo 12 – Compressor

Inspection Photos
Location Name: Pronghorn F-22 PAD
Location ID: 437437



Photo 13 – Separators



Photo 14 – Separators

Inspection Photos
Location Name: Pronghorn F-22 PAD
Location ID: 437437



Photo 15 – Unmarked Risers North of Separators

Photo 16 – Gas Lift Injection Meter House

Inspection Photos
Location Name: Pronghorn F-22 PAD
Location ID: 437437



Photo 17 – Unmarked Riser, Labels missing, Cover also missing at Maintenance Tank on East Side of Location

Photo 18 – Maintenance Tanks