

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1SENW

Location ID: 311586



Photo #5633 from entrance to location.



Photo #5634 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1SENW

Location ID: 311586



Photo #5635 from entrance to location.



Photo #5636 No battery sign located at the tank battery.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1SENW

Location ID: 311586



Photo #5637 Storage tank not labeled.



Photo #5638 Sight glass indicates the storage tank is full of an unknown fluid.