

Final Reclamation Inspection

January 11, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 415637

Inspection Document #: 697503621

Weld County, CO

NWNE Section 35 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. Photo taken from the eastern well location access road, facing West. Photo illustrates Operator has performed final reclamation activities. Snow cover inhibited Staff's ability to perform a thorough reclamation inspection; therefore, Staff will not make a final assessment for reclamation at this time.

Inspection Photos

Location Name: 70 Ranch USX BB 35-02

Location ID: 415637



Photo 2. Photo taken from the eastern well location, facing Southwest. See comments under Photo 1.



Photo 3. Photo taken from the eastern well location, facing Northwest. See comments under Photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503621

Inspection Photos
Location Name: 70 Ranch USX BB 35-02
Location ID: 415637



Photo 4. Photo taken from the offsite tank battery location, facing South. Photo illustrates the tank battery is still in use for other nearby active wells.

