



Photo 1: Underwood Ditch (OWP) #2 prior to plugging. Wellbore fluid sample collected from within casing, 11/2/2021.




Photo 2: SS01 collected adjacent to Underwood Ditch (OWP) #2 P&A marker, 11/19/2021.