

Inspection Photos
Location Name: Walter Hunziker 1
Location ID: 317632



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Walter Hunziker 1
Location ID: 317632



Photo 3 Pump Jack



Photo 4 Ancillary equip.

Inspection Photos
Location Name: Walter Hunziker 1
Location ID: 317632



Photo 5 TB sign



Photo 6 TB

Inspection Photos
Location Name: Walter Hunziker 1
Location ID: 317632



Photo 7 PW tank



Photo 8 Horiz. Heated Sep.

Inspection Photos
Location Name: Walter Hunziker 1
Location ID: 317632



Photo 9 Gas Meter Run




Photo 10 Card in meter box indicates calibration is not current