

Inspection Photos

API: 071-07471

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/27/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07471 | Date: 1/27/2022

Inspection Photos



Photo 1. This area of erosion is along the road to Madrid Canyon at Lat/Long:37.10498,-104.67915.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07471 | Date: 1/27/2022

Inspection Photos



Photo 2. Facing northwest toward the access road. There is a pile of rock rip/rap which appears to have been placed here for bank stabilization and stormwater repairs.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07471 | Date: 1/27/2022

Inspection Photos



Photo 3. The is areas of erosion along the road side traveling to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07471 | Date: 1/27/2022

Inspection Photos



Photo 4. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07471 | Date: 1/27/2022

Inspection Photos



Photo 5. Well sign is posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07471 | Date: 1/27/2022

Inspection Photos



Photo 6. The fence around the pit is not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07471 | Date: 1/27/2022