

# Final Reclamation Inspection

December 15th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 332813

Inspection Document #: 701900291

SESE Section 31 T4N R66W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Wolf 44-31  
Location ID: 332813



**Photo 1.** 2021 aerial imagery of the well pad and tank battery (north is up).

Inspection Photos  
Location Name: Wolf 44-31  
Location ID: 336478



**Photo 2.** Overview photo of the well pad taken from the northern edge looking south. Note: no vegetation establishment within the well pad.

Inspection Photos  
Location Name: Wolf 44-31  
Location ID: 336478



**Photo 3.** Overview photo of the tank battery taken at ground level from the northern edge looking south. Note: no desirable species observed.