

Final Reclamation Inspection

December 15th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323171

Inspection Document #: 701900293

NWNW Section 24 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Nadine 1-24
Location ID: 323171



Photo 1. 2021 aerial imagery of the well pad and tank battery (north is up).
Note: The well pad now resides in an industrial lot.

Inspection Photos
Location Name: Nadine 1-24
Location ID: 336478



Photo 2. Overview photo of the well pad taken from the eastern edge looking west.

Inspection Photos
Location Name: Nadine 1-24
Location ID: 336478



Photo 3. Overview photo of the tank battery taken at ground level from the eastern edge looking west.

Inspection Photos
Location Name: Nadine 1-24
Location ID: 336478



Photo 4. Photos taken from the middle of the tank battery. Left photo facing north and right photo facing east. See description under photo 5.

Inspection Photos
Location Name: Nadine 1-24
Location ID: 336478



Photo 5. Photo taken from the middle of the tank battery. Left photo facing south and right photo facing west. Limited plant establishment observed.

Inspection Photos
Location Name: Nadine 1-24
Location ID: 336478



Photo 6. Gravel stock observed on the eastern edge of the tank battery.