

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DUTTON FAMILY LIMITED-68S96W /1SESE

Location ID: 334368




Photo #5791 Caerus Access road.




Photo #5792 Caerus access road.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DUTTON FAMILY LIMITED-68S96W /1SESE

Location ID: 334368



Photo #5793 Insufficient tracking controls.



Photo #5795 Tracking occurring on to county road 306.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DUTTON FAMILY LIMITED-68S96W /1SESE

Location ID: 334368



Photo #5796 Tracking occurring on to county road 306.



Photo #5797 Insufficient tracking BMP.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DUTTON FAMILY LIMITED-68S96W /1SESE

Location ID: 334368



**Photo #5798 Tracking occurring for approximately 100 yards on to County road 306.**