

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEPT OF ENERGY-66S95W /32SWNE

Location ID: 335246



Photo #5813 from entrance to location.



Photo #5814 Location lacks stabilization.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEPT OF ENERGY-66S95W /32SWNE

Location ID: 335246



**Photo #5815 Location lacks stabilization.**



**Photo #5816 Location lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEPT OF ENERGY-66S95W /32SWNE

Location ID: 335246



**Photo #5817 Insufficient tracking BMP at entrance to location.**