

Inspection Photos  
Location Name: Carter 21-33  
Location ID: 329511



Photo 1 WH sign



Photo 2 WH

**Inspection Photos**  
**Location Name: Carter 21-33**  
**Location ID: 329511**



**Photo 3 Pump Jack**



**Photo 4 ancillary equip.**

Inspection Photos  
Location Name: Carter 21-33  
Location ID: 329511



Photo 5 TB sign



Photo 6 TB.

**Inspection Photos**  
**Location Name: Carter 21-33**  
**Location ID: 329511**



**Photo 7 Gas Meter Run no indication of calibration status**



**Photo 8 Horiz. Heated Sep..**