



ADO OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION FORM



<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 075 - 06500		LEASE NAME: Kirk A-2	
LOCATION: NWSW 17-9N-53		OPERATOR: Timka Res.	
DATE: 8-22-95		INSPECTOR: Ed Binkley	
Insp. Type: CA	Insp. Status: PA	PA: Y <input checked="" type="radio"/> N <input checked="" type="radio"/>	Pass/Fail: P <input checked="" type="radio"/> F <input checked="" type="radio"/> Viol.: Y <input checked="" type="radio"/> N <input checked="" type="radio"/> NOV: Y <input checked="" type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs	N/A	
Pits (Reserve/Production)		
Fences	Oil BP w/ 25x @ Perst 855W	
Tank Battery Equipment	50 5x @ 800' 40 5x @ 221' 10 5x @ 40' } order by Dave Dillon	
Fire Walls/Berms/Dikes	Cement fell 100' down hole	
General Housekeeping	install 5 5x top plug.	
Spills (Oil/Water)		
Bradenhead		
Drilling Well/Workover	Timka Resources Rig over hole Cementers Inc pumping cement plugs.	
Surface Rehabilitation	Fallow field - grass	
Miscellaneous	Tim & John Pivonka on site.	

CORRECTIVE ACTION REQUIRED: Restore surface.

Date Corrective Action Required By: 2-18-96

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

