

Construction and Stormwater Inspection

January 26, 2022

Operator: NOBLE ENERGY INC- #100322

Location ID: 459867

Inspection Document #: 697503666

Weld County, CO

NENW Section 1 T3N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources




Photo 1. Photo taken from the entrance of location, facing North. Photo illustrates Operator has installed a mailbox with required permits.

Inspection Photos
Location Name: D01-03 /Multi
Location ID: 459867



Photo 2. Photo taken from the entrance of location, facing South. Photo illustrates temporarily BMPs have been installed around the perimeter of location. Frozen soil conditions were observed at the time of this inspection.



Photo 3. Photo taken from the southern location, facing West. See comments under Photo 2.

Inspection Photos
Location Name: D01-03 /Multi
Location ID: 459867



Photo 4. Photo taken from the northern location, facing West. See comments under Photo 2.



Photo 5. Photo taken from the northern location, facing East. Photo illustrates the approximate area for the detention pond being constructed per Weld County requirements.



Photo 6. Photo taken from the western facility pad, facing East. Photo illustrates Operator has is importing fill material to the location.