

Inspection Photos  
Operator: Simcoe  
API: 067-09040  
Date: 1/31/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of northern project area from the northwestern corner facing eastward. Vegetation largely snow covered, western wheatgrass and sand dropseed are observable. Trailer stored on well pad in portions that may not be needed for production operations.



Photo 3. View of reference area comprised of open grass field with scattered pinyon, juniper and gambel oak trees.