

Inspection Photos

API: 009-06014

Operator: JONES ENERGY

Inspection Date: 2/1/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06014 | Date: 2/1/2022

Inspection Photos



Photo 1. Drone aerial photo facing southwest toward the former access road. There is mostly undesirable weeds (Kochia) at the beginning portion of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06014 | Date: 2/1/2022

Inspection Photos



Photo 2. Drone aerial photo facing southwest toward the abandoned well site. The site still remains bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06014 | Date: 2/1/2022

Inspection Photos




Photo 3. Drone aerial photo facing northeast toward the abandoned well site. The site still remains bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06014 | Date: 2/1/2022