

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-66S95W /32SESE

Location ID: 323885



Photo #5880 from entrance to location.



Photo #5881 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-66S95W /32SESE

Location ID: 323885



Photo #5882 Insufficient tracking BMP located at entrance to location.