

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE-67S95W /20NESE

Location ID: 335039



Photo #5883 from entrance to location.



Photo #5884 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE-67S95W /20NESE

Location ID: 335039



Photo #5885 No battery sign located at the tank battery.



Photo #5886 Heating insulation open ended and not capped.