

# Final Reclamation Inspection

February 9, 2022

Operator: RED HAWK PETROLEUM LLC- 10503

Location ID: 427036

Inspection Document #: 697503690

Weld County, CO

NENE Section 11 T7N R62W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Conrad #1-11H  
Location ID: 427036



**Photo 1.** COGCC GISOnline 2019 aerial imagery illustrates the location was built. Operator has failed to plug the conductor and has failed to reclaim the location.



Inspection Photos  
Location Name: Conrad #1-11H  
Location ID: 427036



**Photo 2.** Photo taken from the north access road, facing South. Photo illustrates the access road that was constructed for the location.



Inspection Photos  
Location Name: Conrad #1-11H  
Location ID: 427036



**Photo 3.** Photo taken from the north location, facing Southwest. See comments under Photo 1.



**Photo 4.** Photo taken from the central location, facing South. Photo illustrates the conductor at location.



Inspection Photos  
Location Name: Conrad #1-11H  
Location ID: 427036



**Photo 5.** Photo taken from the location. See comments under Photo 4.

Inspection Photos  
Location Name: Conrad #1-11H  
Location ID: 427036



**Photo 6.** Photo taken from the eastern location, facing Northeast. Photo illustrates the topsoil stockpile. Topsoil stockpile was not properly stabilized. There was some erosion evident along the west-facing side.



**Photo 7.** Photo taken from the eastern location, facing Southeast. See comments under Photo 6.



Inspection Photos  
Location Name: Conrad #1-11H  
Location ID: 427036



**Photo 8.** Reference photo taken northwest of location.

