

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /28SENW

Location ID: 335416



Photo #5938 from entrance to location.



Photo #5939 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /28SENW

Location ID: 335416



Photo #5940 Location lacks stabilization.



Photo #5942 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /28SENW

Location ID: 335416



Photo #5941 Insufficient tracking BMP located at the entrance to location.