

Inspection Photos

API: 017-06399

Operator: ANADARKO E&P ONSHORE LLC

Inspection Date: 2/10/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06399 | Date: 2/10/2022

Inspection Photos



Photo 1. Facing toward the location. A uniform desirable vegetation cover has established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06399 | Date: 2/10/2022

Inspection Photos



Photo 2. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06399 | Date: 2/10/2022

Inspection Photos



Photo 3. Facing toward the east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06399 | Date: 2/10/2022

Inspection Photos



Photo 4. Center of the location facing south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06399 | Date: 2/10/2022

Inspection Photos



Photo 5. Center of the location facing north.

