

Inspection Photos
Location Name: Pace-Connelly 1
Location ID: 318533



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Pace-Connelly 1
Location ID: 318533



Photo 3 Unused Pump jack equipment east of WH in the weeds.



Photo 4 Unused Pump jack equipment east of WH in the weeds.

Inspection Photos
Location Name: Pace-Connelly 1
Location ID: 318533



Photo 5 Unused Pump jack equipment east of WH in the weeds.