

Inspection Photos

API: 073-06209

Operator: CITATION OIL & GAS CORP

Inspection Date: 2/11/2022



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 2/11/2022

Inspection Photos




Photo 1. Drone aerial image facing northwest toward the associated abandoned facility. It appears undesirable weeds have been mowed however soils in this area remain compacted and not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 2/11/2022

Inspection Photos



Photo 2. Drone aerial image facing southeast toward the associated abandoned facility. The access points shown at red arrows need to be reclaimed. The fence will need to be put back to the original position.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 2/11/2022

Inspection Photos



Photo 3. Drone aerial photo facing northwest toward the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 2/11/2022

Inspection Photos



Photo 4. Drone aerial photo facing northwest toward the fenced location. The brown vegetation color at the location is undesirable weeds (Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 2/11/2022

Inspection Photos



Photo 5. Facing down toward the location. It appears the weeds at the location had been mowed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 2/11/2022

Inspection Photos



Photo 6. Facing southeast at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06209 | Date: 2/11/2022