

Inspection Photos
Operator: Simcoe
API: 067-09714
Date: 2/15/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with blue grama, sand dropseed, and western wheatgrass.



Photo 3. View of the western portion of the project area from the northwestern corner facing southward.



Photo 4. View of area down-slope from access road where gravel is washed off and deposited outside of the project area. Area is approximately 30ft long and 10ft wide.



Photo 5. View of reference area vegetation comprised of pinyon and juniper woodland with understory of sagebrush, western wheatgrass, blue grama, prickly pear, and yucca.