

Final Reclamation Inspection

February 15, 2022

Operator: VERDAD RESOURCES LLC - #10651

Location ID: 424579

Inspection Document #: 697502320

Weld County, CO

NWNW Section 8 T7N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Pergamos /8-11-7-60
Location ID: 424579



Photo 1. Photo taken from the entrance of location, facing East. Photo illustrates a culvert associated with the location. Culvert is not in use, presents a safety hazard and is debris.

Inspection Photos
Location Name: Pergamos /8-11-7-60
Location ID: 424579



Photo 2. Photo taken from the west location, facing Southeast. Photo illustrates the location is being managed and appears to be progressing towards final reclamation standards.

Inspection Photos
Location Name: Pergamos /8-11-7-60
Location ID: 424579



Photo 3. Photo taken from the west location, facing East. See comments under Photo 2.