

Inspection Photos
Location Name: Noffsinger 11,31-33
Location ID: 472211



COGCC
40.44965, -104.55724, 4591.3ft
02/17/2022 14:16:22

Photo 1: Northwest side of excavation looking southeast.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Noffsinger 11,31-33
Location ID: 472211



Photo 2: Looking at south wall of excavation. Field drain or other utility exposed in wall of excavation.



Inspection Photos
Location Name: Noffsinger 11,31-33
Location ID: 472211



Photo 3: West side of excavation looking northeast.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Noffsinger 11,31-33
Location ID: 472211



Photo 4: West side of excavation looking east.

