

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0705-22-43 Pad

Location ID: 335186



Photo #5983 from entrance to location.



Photo #5984 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0705-22-43 Pad

Location ID: 335186



Photo #5985 Location lacks stabilization.



Photo #5988 Location lacks stabilization.

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0705-22-43 Pad

Location ID: 335186



Photo #5987 Insufficient tracking BMP's at entrance to location.