

Location Name: Dawson A 1 tank battery Location ID/API #: Spill 481653



Location Name: Dawson A 1 tank battery Location ID/API #: Spill 481653



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Spill went through containment walls on south side of
containment.**

Location Name: Dawson A 1 tank battery Location ID/API #: Spill 481653



2/18/22 11:41
38.42370N 102.46441W

Location Name: Dawson A 1 tank battery Location ID/API #: Spill 481653



2/18/22 11:42
38.42360N 102.46452W

Location Name: Dawson A 1 tank battery Location ID/API #: Spill 481653




2/18/22 11:52
38.42367N 102.46466W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Dawson A 1 tank battery Location ID/API #: Spill 481653



Area with soil pile is existing Remediation 20712. Spill flowed into this remediation area and along road ditch.

Location Name: Dawson A 1 tank battery Location ID/API #: Spill 481653



Location Name: Dawson A 1 tank battery Location ID/API #: Spill 481653



Area with soil pile is existing Remediation 20712. Spill flowed into this remediation area and along road ditch.

Location Name: Dawson A 1 tank battery Location ID/API #: Spill 481653

