

Final Reclamation Inspection

November 9th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 432119

Inspection Document #: 701900324

SWSW Section 2 T2N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Waste Management 2I-221
Location ID: 432119



Photo 1. 2021 aerial imagery of the well pad. The tank battery (highlighted in blue) remains to service the producing wells on site. Note: erosion issues observed at tank battery, refer to photo 3.

Inspection Photos
Location Name: Waste Management 2I-221
Location ID: 432119



Photo 2. Overview photo of the reclaimed well taken at ground level from the south edge looking north.

Inspection Photos
Location Name: Waste Management 2I-221
Location ID: 432119



Photo 3. Rill erosion located on northern edge of active tank battery.