

# Final Reclamation Inspection

November 10th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 436366

Inspection Document #: 701900330

Weld County, CO

NENW Section 5 T3N R64W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Becker Ranch 5J-323  
Location ID: 436366



**Photo 1.** 2021 aerial imagery of the well pad (north is up). The tank battery highlighted in blue remains for the producing wells on site.

Inspection Photos  
Location Name: Becker Ranch 5J-323  
Location ID: 436366



**Photo 2.** Overview photo of the reclaimed well taken at ground level from the east edge looking west.

Inspection Photos  
Location Name: Becker Ranch 5J-323  
Location ID: 436366



**Photo 3.** Tank battery remains for the producing wells on site.

Inspection Photos  
Location Name: Becker Ranch 5J-323  
Location ID: 436366



**Photo 4.** Rill erosion observed on the northeastern edge of the tank battery.