

Final Reclamation Inspection

November 16th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 332809

Inspection Document #: 701900338

NWSW Section 28 T5N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Adamson 1-6I
Location ID: 332809



Photo 1. 2021 aerial imagery of the well pad (north is up). The tank battery highlighted in blue remains in service for the producing wells on site.

Inspection Photos
Location Name: Adamson 1-6I
Location ID: 332809



Photo 2. Overview photo of the reclaimed well taken at ground level from the northern edge looking south. Note: Producing well remains on site.

Inspection Photos
Location Name: Adamson 1-6I
Location ID: 332809



Photo 3. Rill erosion observed on the western edge of the tank battery.