

Inspection Photos

API: 071-07901

Operator: OGRIS OPERATING LLC

Inspection Date: 2/22/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07901 | Date: 2/22/2022

Inspection Photos



Photo 1. Facing southwest toward the wellsite. The vegetation is well established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07901 | Date: 2/22/2022

Inspection Photos



Photo 3. The engine is abnormally loud and it looks like the muffler needs maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07901 | Date: 2/22/2022