

Inspection Photos

API: 073-06489

Operator: WIEPKING-FULLERTON ENERGY

Inspection Date: 2/11/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06489 | Date: 2/11/2022

Inspection Photos



Photo 1. Facing west toward the former access road. The desirable vegetation has reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06489 | Date: 2/11/2022

Inspection Photos



Photo 2. Center of the location facing west. The desirable vegetation has reestablished throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06489 | Date: 2/11/2022

Inspection Photos



Photo 3. Center of the location facing east. The desirable vegetation has reestablished throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06489 | Date: 2/11/2022

Inspection Photos




Photo 4. Facing southwest at the beginning of the vegetation transect at the location.



Photo 5. Facing northeast at the end of the vegetation transect at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06489 | Date: 2/11/2022

Inspection Photos



Photo 6. Facing southeast at the beginning of the vegetation transect at the reference area.



Photo 7. Facing northwest at the end of the vegetation transect at the reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06489 | Date: 2/11/2022

Inspection Photos

Cover Data

Date: 2/11/22

Inspected By:

Location/Operator:

APF: 073-06429

Inspected By: Ryan Costa

Weipk. - 9. Ell. b. - 1. Ell.

Transect #/disturbed/Ref	Location/Operator	Alt.	0.05	00467	akpk: 9 Fuller Ave Eng				
Transect Orientation and first photo, degrees	Y. disturbed 59.20311 -103.55172	SW	Ref. on road 59.20301 -103.55119	SE					
Photo Midpoint (2)	NW, SE		NE, SW						
End transect	39.20307 -103.55009	NE	39.20276 -103.55094	NW					
Photo other									
Aspect/Slope	2-5% E		2-5% E						
		Totals		Totals		Totals		Totals	
Cryptogams (eg. Moss, lichen)									
Litter		31		40					
Bare Soil	:1	45	L	37					
Rock									
Total Weeds	5								
Total Desirable Species	19		27						
80% Check	19/22 = 82%								
	1st Hit	2nd/P	1st Hit	2nd/P	1st Hit	2nd/P	1st Hit	2nd/P	
Spruce		11		6					
Pine		2		9					
Salix		6							
Aspen		3		4					
Sunflower	.	1	P						
Asioli	.	1	:	2					
Botany		.	.	1					
Pine cone		.	.	1					
unknown bird	P		P						

2nd= second hit; P= plant species present but not hit



COLORADO

Oil & Gas Conservation Commission

Department of Natural Resources

API: 073-06489 | Date: 2/11/2022