

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NESW

Location ID: 334897



Photo #6011 from entrance to location.



Photo #6012 Vent pipe on tank open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NESW

Location ID: 334897



Photo #6013 Unused equipment in tank containment