

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 1 – Pumping Unit



Photo 2 – Tank Battery Sign



Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 3 – ECD



Photo 4 – Sales Line STILL LOTO



Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 5 – Valves NOW Open



Photo 6 – ECD – Valves Open

Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707



Photo 7 – Produced Water Tank NFA is starting to fade



Photo 8 – Content and Capacity on Middle Oil Tank is starting to fade