

Inspection Photos

API: 071-07623

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/25/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07623 | Date: 2/25/2022

Inspection Photos



Photo 1. Facing southeast toward the wellsite.



Inspection Photos



Photo 2. There appears to be a water leak near the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07623 | Date: 2/25/2022