

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /35SWSW

Location ID: 334773



Photo #6056 from entrance to location.



Photo #6057 from entrance to location.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /35SWSW

Location ID: 334773



**Photo #6058 Location lacks stabilization.**



**Photo #6059 Location lacks stabilization.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /35SWSW

Location ID: 334773



Photo #5467 from inspection #699803900 conducted on 12/21/21.



Photo #6060 Insufficient tracking BMP located at entrance to location.