

LASO OIL & GAS LLC
CONTINENTAL-63S100W 17SESW
Location # 315226



Sign is illegible. Sign is hung upside down. Sign was made for another well and has this wells information written over the old information. The Api # is not correct. Well name and legal description is illegible.



LASSO OIL & GAS LLC CONTINENTAL-63S100W 17SES Location # 315226



Meter last calibrated in 2019.

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 17SESW
Location # 315226



No braden head access. Dead debris around well, equipment and tank.



Surface casing open to atmosphere.

**LASSO OIL & GAS LLC
CONTINENTAL-63S100W 17SESW
Location # 315226**



Heat equipment disassembled from heated separator. Open access to wildlife.



Dead debris around equipment.

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 17SESW
Location # 315226



Label doesn't meet Rule 605.h. (missing information). No NFPA sticker, no operator name and no operator contact number.



No battery sign at tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 17SESW
Location # 315226



Sign is illegible.

Dead debris around equipment

LASSO OIL & GAS LLC
CONTINENTAL-63S100W 17SESW
Location # 315226



Dead debris around equipment