

Final Reclamation Inspection

February 25, 2022

Operator: BURLINGTON RESOURCES OIL & GAS LP- 26580

Location ID: 449806

Inspection Document #: 697503754

Arapahoe County, CO

NWSW Section 28 T4S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: RUSH 4-65 29-30 /3AH
Location ID: 449806



Photo 1. Photo taken from the northwestern location, facing East. Photo illustrates two (SI and TA) of the six wells on location.

Inspection Photos
Location Name: RUSH 4-65 29-30 /3AH
Location ID: 449806



Photo 2. Photo taken from the southeastern location, facing East. Photo illustrates four of the six wells on location.

