

Caerus Piceance LLC  
L4E  
Location # 323955



Location/lack of battery signage



location

Caerus Piceance LLC  
L4E  
Location # 323955



Location



Load line



Caerus Piceance LLC  
L4E  
Location # 323955



Open exhaust thaw lines



Caerus Piceance LLC  
L4E  
Location # 323955



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**

