

# Final Reclamation Inspection

February 25, 2022

Operator: AXIS EXPLORATION LLC - #10646

Location ID: 320750

Inspection Document #: 697503762

Arapahoe County, CO

SENE Section 16 T4S R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: COLUMBINE-STATE #2  
Location ID: 320750



**Photo 1.** Photo taken from the eastern well location access road, facing North. Photo illustrates the access road is evident with some vegetation but the road goes beyond the well location onto another portion of the surface owners property.

Inspection Photos  
Location Name: COLUMBINE-STATE #2  
Location ID: 320750



**Photo 2.** Photo taken from the associated tank battery, facing East. Photo illustrates all equipment has been removed. It appears the Operator is performing weed management, as Kochia looked to be mowed. There was desirable vegetation observed throughout portion of the tank battery.



**Photo 3.** Photo taken from the associated tank battery, facing North. See comments under Photo 2.

Inspection Photos  
Location Name: COLUMBINE-STATE #2  
Location ID: 320750



**Photo 4.** Photo taken from the associated tank battery, facing West. See comments under Photo 2.



**Photo 5.** Photo taken from the well location, facing East. Photo illustrates the well location appears to be reflective of reference area vegetation.

Inspection Photos  
Location Name: COLUMBINE-STATE #2  
Location ID: 320750



**Photo 6.** Reference photo taken south of the tank battery, facing South. Photo illustrates the reference area vegetation is primarily dominated by Sand dropseed.

