

Inspection Photos  
Location Name: Horsetail 07 West CPB  
Location ID: 439324



Photo 1 – Heater Treaters



Photo 2 – Tank Battery Sign

**Inspection Photos**  
**Location Name: Horsetail 07 West CPB**  
**Location ID: 439324**



**Photo 3 – Production Equipment**

**Photo 4 – Production Equipment**

**Inspection Photos**  
**Location Name: Horsetail 07 West CPB**  
**Location ID: 439324**



**Photo 5 – Tank Battery**



**Photo 6 – Produced Water Tanks**

**Inspection Photos**  
**Location Name: Horsetail 07 West CPB**  
**Location ID: 439324**



**Photo 7– Water LACTs**

**Photo 8 – Oil LACTs**

**Inspection Photos**  
**Location Name: Horsetail 07 West CPB**  
**Location ID: 439324**



**Photo 9 – VRTs**

**Photo 10 – ECD and Flare**

**Inspection Photos**  
**Location Name: Horsetail 07 West CPB**  
**Location ID: 439324**



**Photo 11 – Production Equipment**

**Photo 12 – Production Equipment**

**Inspection Photos**  
**Location Name: Horsetail 07 West CPB**  
**Location ID: 439324**



**Photo 13 – Heater Treaters**



**Photo 14 – North Compressor**

**Inspection Photos**  
**Location Name: Horsetail 07 West CPB**  
**Location ID: 439324**



**Photo 15 – South Compressor**



**Photo 16 – Unmarked Riser**

**Inspection Photos**  
**Location Name: Horsetail 07 West CPB**  
**Location ID: 439324**



**Photo 17 – Unmarked Risers**

**Photo 18 – Unmarked Risers**