

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Colorado Oil and Gas Conservation Commission
40.86035, -103.78228, 4889.9ft, 285°
03/01/2022 14:53:08



Colorado Oil and Gas Conservation Commission
40.85992, -103.78347, 4841.0ft, 255°
03/01/2022 14:47:17

Photo 1 – Signs at Entrance

Photo 2 – South Wellheads



Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741




Photo 3 – Unused Wellhead Parts

Photo 4 – Gas Lift Injection Meter Shed

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Colorado Oil and Gas Conservation Commission
40.8599, -103.78336, 4944.9ft, 241°
03/01/2022 14:48:23



Colorado Oil and Gas Conservation Commission
40.85916, -103.78364, 4910.0ft, 226°
03/01/2022 14:49:17

Photo 5 – North Wellheads

Photo 6 – Gas Lift Injection Meter Shed

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Photo 7 – Heater Treaters

Photo 8 – Production Equipment

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Colorado Oil and Gas Conservation Commission
40.85945, -103.78423, 4898.9ft, 273°
03/01/2022 14:49:59



Colorado Oil and Gas Conservation Commission
40.85949, -103.78422, 4901.3ft, 281°
03/01/2022 14:50:03

Photo 9 – Production Equipment

Photo 10 – Compressor

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Colorado Oil and Gas Conservation Commission
40.85979, -103.7843, 4901.4ft, 261°
03/01/2022 14:50:23



Colorado Oil and Gas Conservation Commission
40.8598, -103.78431, 4907.8ft, 280°
03/01/2022 14:50:26

Photo 11 – VRT

Photo 12 – Tank Battery

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Photo 13 – Tank Battery

Photo 14 – Water LACTS

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Colorado Oil and Gas Conservation Commission
40.8599, -103.78454, 4931.2ft, 196°
03/01/2022 14:51:19

Photo 15 – VRT and Oil LACT