

Inspection Photos  
Location Name: Razor 12H PAD  
Location ID: 430096



Photo 1 – Tank Battery Sign

Photo 2 – Wellhead

**Inspection Photos**  
**Location Name: Razor 12H PAD**  
**Location ID: 430096**



Colorado Oil and Gas Conservation Commission  
40.85399, -103.80653, 4888.4ft, 260°  
03/02/2022 13:00:05



Colorado Oil and Gas Conservation Commission  
40.8538, -103.80641, 4896.2ft, 262°  
03/02/2022 13:00:52

**Photo 3 – North Wellheads**

**Photo 4 – South Wellheads**

**Inspection Photos**  
**Location Name: Razor 12H PAD**  
**Location ID: 430096**



**Photo 5 – Flare and ECD**



**Photo 6 – VRUs**

**Inspection Photos**  
**Location Name: Razor 12H PAD**  
**Location ID: 430096**



**Photo 7 – Tank Battery**

**Photo 8 – Unmarked Risers**

**Inspection Photos**  
**Location Name: Razor 12H PAD**  
**Location ID: 430096**



**Photo 9 – Unmarked Risers**

**Photo 10 – Unmarked Risers**

**Inspection Photos**  
**Location Name: Razor 12H PAD**  
**Location ID: 430096**



**Photo 11 – Compressor**

**Photo 12 – Production Equipment**

**Inspection Photos**  
**Location Name: Razor 12H PAD**  
**Location ID: 430096**



**Photo 13 – Heater Treaters**

**Photo 14 – Gas Lift Injection Meter Sheds**