

Inspection Photos
Location Name: Razor 12F PAD
Location ID: 435656



Photo 1 – Tank Battery Sign

Photo 2 – Compressors

Inspection Photos
Location Name: Razor 12F PAD
Location ID: 435656



Photo 3 – Unmarked Risers and Stained Soil West of Compressors

Photo 4 – Gas Lift Injection Meter Sheds

Inspection Photos
Location Name: Razor 12F PAD
Location ID: 435656



Photo 5 – 12F-1303A Stained Soil

Photo 6 – 12F-1303A Stained Soil

Inspection Photos
Location Name: Razor 12F PAD
Location ID: 435656



Colorado Oil and Gas Conservation Commission
40.8544, -103.81817, 4892.0ft, 12°
03/02/2022 13:13:54



Colorado Oil and Gas Conservation Commission
40.85474, -103.81743, 4998.3ft, 174°
03/02/2022 13:14:26

Photo 7 – 12F-1303A Stained Soil

Photo 8 – South Wellheads

Inspection Photos
Location Name: Razor 12F PAD
Location ID: 435656



Photo 9 – North Wellheads



Photo 10 – Heater Treaters

Inspection Photos
Location Name: Razor 12F PAD
Location ID: 435656



Photo 11 – Unmarked Riser

Photo 12 – VRUs and VRTs

Inspection Photos
Location Name: Razor 12F PAD
Location ID: 435656



Colorado Oil and Gas Conservation Commission
40.855, -103.8172, 4894.5ft, 169°
03/02/2022 13:16:09

Photo 13 – Tank Battery



Colorado Oil and Gas Conservation Commission
40.85418, -103.81714, 4893.4ft, 169°
03/02/2022 13:16:39

Photo 14 – ECD and Flare

Inspection Photos
Location Name: Razor 12F PAD
Location ID: 435656



Photo 15 – Electrical Shed



Photo 16 – LACTs