

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SESW

Location ID: 334749



Photo #6080 from entrance to location.




Photo #6081 Location lacks stabiiztion.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SESW

Location ID: 334749



**Photo #6082** Location lacks stabilization.



**Photo #6083** Insufficient tracking BMP at entrance to location .