

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401435998

Date Received:
10/20/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 77330

Name of Operator: SG INTERESTS I LTD

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

 970-385-0696 inspection@sginterests.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602093

Inspection Date: 10/17/2017

FIR Submit Date: 10/17/2017

FIR Status: _____

Inspected Operator Information:

Company Name: SG INTERESTS I LTD

Company Number: 77330

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

LOCATION - Location ID: 440803

Location Name: Falcon Seaboard 11-90-12 Number: 3 County: _____

Qtrqr: NESW Sec: 12 Twp: 11S Range: 90W Meridian: 6

Latitude: 39.112410 Longitude: -107.399380

FACILITY - API Number: 05-051-00 Facility ID: 440803

Facility Name: Falcon Seaboard 11-90-12 Number: 3

Qtrqr: NESW Sec: 12 Twp: 11S Range: 90W Meridian: 6

Latitude: 39.112410 Longitude: -107.399380

CORRECTIVE ACTIONS:

1 CA# 106019

Corrective Action: Contact COGCC EPS staff, Jim Hughes at 970-903-4072 within 48 hours.

Date: 10/19/2017

Response: CA COMPLETED

Date of Completion: 10/18/2017

Operator Comment: SG contacted Jim Hughes to discuss results of the inspection on Wednesday (10/18/2017) morning. The inspection took place during removal of equipment used for completion operations. This week was SG's first availability to get a vacuum truck to the location and conduct clean-up activities due to the surface of the location being occupied by equipment and only partially visible the last two weeks. The vacuum truck cleaned out the cellars, and crews are currently scrubbing the well head to clean normal build-up on the well heads. Oily stains from engines were treated with microbes; any remaining material will be pick up and disposed of properly. Free standing fluid near the frac tanks was soaked up using soaker pads. The fluid is anticipated to be rainwater mixed with rust from the bottom of the frac tanks, however SG will conduct a soil test per table 910-1 to ensure soil is

within standards. SG continues to conduct clean-up activities in the same manner as all demobilizing operations.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: SG contacted Jim Hughes to discuss results of the inspection on Wednesday (10/18/2017) morning. The inspection took place during removal of equipment used for completion operations. This week was SG's first availability to get a vacuum truck to the location and conduct clean-up activities due to the surface of the location being occupied by equipment and only partially visible the last two weeks. The vacuum truck cleaned out the cellars, and crews are currently scrubbing the well head to clean normal build-up on the well heads. Oily stains from engines were treated with microbes; any remaining material will be pick up and disposed of properly. Free standing fluid near the frac tanks was soaked up using soaker pads. The fluid is anticipated to be rainwater mixed with rust from the bottom of the frac tanks, however SG will conduct a soil test per table 910-1 to ensure soil is within standards. SG continues to conduct clean-up activities in the same manner as all demobilizing operations.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Blanchard

Signed: _____

Title: Env. & Reg Manager

Date: 10/20/2017 3:14:10 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401435998	FIR RESOLUTION FORM
401556687	FIR RESOLUTION SUBMITTED

Total Attach: 2 Files