

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402127895

Date Received:
07/30/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Jessica Dooling

Phone

970-675-4122

Email

jessica_dooling@xtoenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 679704897

Inspection Date: 07/26/2019

FIR Submit Date: 07/26/2019

FIR Status: _____

Inspected Operator Information:

Company Name: XTO ENERGY INC

Company Number: 100264

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

LOCATION - Location ID: 311838

Location Name: PICEANCE CREEK UNIT-61S96W Number: 29SENW County: RIO BLANCO

Qtrqtr: SENW Sec: 29 Twp: 1S Range: 96W Meridian: 6

Latitude: 39.943430 Longitude: -108.194240

FACILITY - API Number: 05-103- -00 Facility ID: 261058

Facility Name: PICEANCE CREEK UNIT Number: T33X-29G

Qtrqtr: SENW Sec: 29 Twp: 1S Range: 96W Meridian: 6

Latitude: 39.943430 Longitude: -108.194240

CORRECTIVE ACTIONS:

1 ☒ CA# 128608

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 08/16/2019

Response: CA COMPLETED

Date of Completion: 07/29/2019

Operator Comment: Guy line markers were installed 7/29/2019, please see attached photo.

COGCC Decision: Approved pending re-inspection

Comply with Rule 603.f .

Date: 08/26/2019

Date of Completion: 07/29/2019

Trach including electrical conduit was removed from location 7/29/2019, plesae see attached photo.

Approved pending re-inspection

Install sign to comply with Rule 210.b.

Date: 08/26/2019

Date of Completion: 07/30/2019

911 was added to sign 7/30/2019, please see attached photo.

Approved pending re-inspection

OPERATOR COMMENT AND SUBMITTAL

All corrective actions were completed on 7/29/2019 and 7/30/2019, please see attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Dooling

Title: Regulatory Coordinator

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402127895	FIR RESOLUTION FORM
402127910	7/29/2019 Dead Men Marker Installed
402127916	7/29/2019 trash removal completed
402127919	7/30/2019 911 Added to Sign
402148169	FIR RESOLUTION SUBMITTED

Total Attach: 5 Files